SB-01-12-23-1 Rev A

DATE RELEASED

01-12-2023

DATE EFFECTIVE

01-12-2023

SUBJECT

Elevator Idler Fatigue Cracks

EFFECTIVITY

MODEL- Ranger R7

SERIAL NO: ALL AIRCRAFT

REASON

Fatigue cracks have been reported in the field on the bracketry supporting the elevator pushrod idler assembly. This is due to high loads from the elevator pushrod fatiguing the bracket through cyclic loading. It is also believed that corrosion of the idler also contributes to this issue. If a crack continues to propagate without proper attention, this could lead to slop in the elevator control system and possibly failure of the supporting bracketry.

REQUIRED ACTION

Inspect bracket and fuselage ribs for cracks. Also note on condition of idler assembly.

TYPE OF MAINTENANCE

Low (may require borescope).

MINIMUM LEVEL OF CERTIFICATION

Owner (may require borescope).

TIME OF COMPLIANCE

Inspect within the next 10hrs of flight time, then in 25 hr intervals until 100hrs has been reached. After this, inspection interval can default to annual inspections.

METHOD OF COMPLIANCE

Inspect the critical flanges as shown in Figure 2 and Figure 3. If any cracks are present, contact Vashon Aircraft Support for corrective action until a subsequent bulletin is released.

Corrosion on the idler, as shown in figure 4, is noteworthy but not indicative of a safety concern.

LABOR REQUIRED:

None at this time.





Figure 1

VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944 SUPPORT@VASHONAIRCRAFT.COM


SB-01-12-23-1 REV A Page **2** of **5**


SERVICE BULLETIN





SERVICE BULLETIN






DETAIL B

Figure 3

SERVICE BULLETIN



PARTS HIDDEN FOR CLARITY




Figure 4