Light Sport Aircraft

SERVICE BULLETIN



SB-12-06-22-1 Rev C

DATE RELEASED

12-06-22

DATE EFFECTIVE

12-06-22

SUBJECT

Engine Mount Fatigue Cracks

EFFECTIVITY

MODEL- Ranger R7

SERIAL NO: ALL AIRCRAFT WITH SERIAL NUMBER LESS THAN 10203

REASON

Fatigue cracks have been reported on the engine mount lug welds caused by insufficient weld fillets. This issue has been traced back to batch of aircraft with serial number identified above.

REQUIRED ACTION

Inspect the engine mounting weldment for cracks.

TYPE OF MAINTENANCE

Low for inspection. High if replacement required.

MINIMUM LEVEL OF CERTIFICATION

Owner for inspection. A&P if replacement is required.

TIME OF COMPLIANCE

Mandatory before further flight. If no cracks are present the following intervals are valid:

- Inspect at interval of 10hrs flight time since service bulletin effectivity.
- After two 10hrs inspection (20hrs total), inspect every 25hrs of flight time.
- Once two 25hrs inspections (total 70hrs) have been conducted, the inspection interval can be same as annual maintenance period (every 100hrs).

If the engine mount has been replaced in accordance with Appendix B of this Service Bulletin the inspection period can be terminated.


METHOD OF COMPLIANCE

Inspect weldment as shown in Appendix A. If any cracks are present, DO NOT continue to fly – Contact Vashon Aircraft Support for corrective action.


Once parts have been obtained from Vashon Aircraft the engine mount can be replaced in accordance with Appendix B of this Service Bulletin. This will require the work of an A&P with a properly equipped shop.





Appendix A: Inspection Of Engine Mount






















Light Sport Aircraft


SERVICE BULLETIN



THIS PAGE INTENTIONALLY LEFT BLANK




Appendix B: Replacement Of Engine Mount




VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944






VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944






VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944






VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944










VASHON AIRCRAFT
14929 141st PL NE Woodinville, WA 98072
425.527.9944
SUPPORT@VASHONAIRCRAFT.COM


SB-12-06-22-1 REV C Page **11** of **25**






VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944











VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944









VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944










VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944
















REMOVE SCREW AND KEEP.

NOTE: ARM WILL POP UP WHEN SCREW IS REMOVED)



NOTE: DO NOT LOSE SPRING AND KEY -




DURING REINSTALLATION; REPLACE AND CLAMP WASHER FLANGES.
MCFARLANE PART NUMBER 78-A109











VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944














NOTE: ENGINE WILL STILL BE CONNECTED WITH CABLING AND IS NOT SHOWN IN IMAGE

VASHON AIRCRAFT 14929 141st PL NE Woodinville, WA 98072 425.527.9944

SB-12-06-22-1 REV C Page **24** of **25**



ONCE COMPLETE REINSTALL USING STEPS IN REVERSE ORDER